



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

MARY ANN WRIGHT  
Acting Division Director

Supervisor Dez

### Inspection Report Minerals Regulatory Program

Report Date: February 14, 2005

**Mine Name:** East Veyo Cinder Knoll

**Operator or Permittee Name:**

Sunroc Corporation

**Permittee Mailing Address:**

180 North 300 East

St. George, Utah 84770

**Permit number:** S/053/067

**Inspection Date:** February 1, 2005

**Inspector(s):** Doug Jensen

**Other Participants:** None

**Permit Status:** Active

**Current Acreages:**

**Total Permitted (Bonded):** <5 Acres

**Total Disturbed:** <5 Acres

**Weather:** Cool, windy

**Inspection Start Time:** 2:30 PM

**Inspection End Time:** 2:45 PM

**Site location/Area Inspected (i.e. Pit #):**

Site

**Surface Ownership:** BLM

**Mineral Ownership:** BLM

**Mineral Mined:** Cinders

**Type of Mine:** Open Pit

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



Inspection Date: February 2, 2005; Report Date: February 14, 2005  
Page 2 of 2  
S/053/067

**Purpose of Inspection:**

While in the area, I stopped by to check mining progress at the site.

**Inspection Summary:**

The cinder pit established at the site has not grown appreciably since my visit last spring. The disturbance is still much less than 5 acres.


**Directions to the site:**

The site is located ~2 miles northeast of Veyo.

**GPS data:**

None gathered.

**Inspector's Signature**



**Date:** February 14, 2005

DJ:jb

cc:

Sunroc Corporation

Rody Cox, BLM, St George FO

O:\M053-Washington\S0530067-EastVeyoCinderKnoll\inspections\02012005ins.doc